

HP 3458A repair project

<http://xDevs.com/fix/hp3458a/>

A9 LTZ1000 isolation cap
Material : Teflon or PP
Units: mm

